Certificate No. :BKC24094293IC

Certificate of Conformity

Applicant : **Foshan Sound Technology CO., LTD.**
2nd floor, No.2, No. 3, South Honggang Industrial Avenue,
Honggang Village, Lishui Town, Nanhai District, Foshan City.

Manufacturer : **Foshan Sound Technology CO., LTD.**
2nd floor, No.2, No. 3, South Honggang Industrial Avenue,
Honggang Village, Lishui Town, Nanhai District, Foshan City.

Trademark : **CS Audio**

Product : **Professional Power Amplifier**

Model(s) : **(See the following annex)**

Test Standard : **IEC 62321-4:2013+A1:2017**
IEC 62321-5:2013
IEC 62321-6:2015
IEC 62321-7-1:2015
IEC 62321-7-2:2017
IEC 62321-8:2017

The product described above has been tested by us and found in compliance with the council RoHS 2.0 Directive 2011/65/EU Annex II (EU) 2015/863 as last amended by Directive (EU) 2017/2102.It is only valid in connection with the test report number: BKC24062969FR.

RoHS

Manager

Sep. 20, 2024

Shenzhen BKC Testing Co., Ltd.
Room103, 1/F, Huaya Building, Huaya Industrial Park, Yousong Community,
Longhua Subdistrict, Longhua District, Shenzhen, Guangdong, China
Tel: 4000-875-382 0755-84829082 E-mail: bkc@bkc-lab.com
Certificate Search: http://www.bkc-lab.com

Annex 1
Certificate No. :BKC24094293IC

Model(s)

MA8.0, LA5.0, LA7.0, LA10.0, LA100, LA200, LA400, LA600, LA800, LA1000, D200, D800, D1200, D2400, D3600, D5200, D10.4, D14.4, D4.8, D4.6, D4.4, CS400, CS600, CS800, CS1000, CS1300, CS1500, CS1800, CS2000, CS4.8, CS4.10, CS4.13, CS4.15, CS4.20, CS2.6, CS2.8, CS2.10, CS2.13, CS2.15, CS2.18, CS2.20, TD600, TD800, TD1000, TD1300, TD1500, TD1800, TD2000, TD4-1000, TD4-1300, TD4-1500, TD4-1800, TD4-2000, CA6,CA9, CA12, CA18, CA20, MA3.0, MA4.0, MA6.0, MA10.0, MA13.0, MA4.4, MA4.6, MA4.8, MA5.0, PC820, PC860, PC880, MA400, MA600, MA800, MA1000, MA1300, MA2000, MA5000, ME4.0, ME6.0, ME8.0, ME10.0, ME1300, ME4400, ME4600, ME4800, ME5000.F12.T15.BH1200, T400, T600, T800, T1000, T1300, T4400, T4600, T4800, T5000, MT400, MT600, MT800, MT1000, MT1800TD, MT4400, MT4800, MT5000, DS3060II, DS2060II, DS4080II, CS880, VN-400, VN-600, VN-800, VN-1000, VN1300, i-200, i-400, i-600, i-800, i-1000, i-1300, i-1500, i-1800, i-2000, VP4.4, VP4.6, VP4.8, VP5.0, VP1200, VP5200, H8400, H8600, H8800, Liveshow 10US, H8800Pro, XRi8000.IV, XRi5000.II, MA41000, LMA-3.0, LMA-5.0, LMA-6.0, LMA-8.0, LMA-10.0, LMA-12.0, LMA-4.8, LCS-600, LCS-1500, LCS-1800, LCS-4.13, PWS-169, PWS-220, VMA-4.2, VMA-8.2, VMA-13.2, VMA-8.4, PQM4.15, PQM4.20, GS-300, GS-600, GS-800, GS-1000, MA4.13, MA4.15, MT3000, TD-5000PRO, MX-1500, X-4000, KP500, KP700, KP900, KP4900, KP4120, PH412, PH216, PH222

RoHS

Manager

Sep. 20, 2024

Shenzhen BKC Testing Co., Ltd.
Room103, 1/F, Huaya Building, Huaya Industrial Park, Yousong Community,
Longhua Subdistrict, Longhua District, Shenzhen, Guangdong, China
Tel: 4000-875-382 0755-84829082 E-mail: bkc@bkc-lab.com
Certificate Search: http://www.bkc-lab.com